

Release Note KL-3T VA1 v2.11.27.68


(This version is only compatible with the new HW version – VA1)

Device Hardware Version

1. Please find your device serial number (S/N), it can be found either on the label or on the web Administration page.

/	4 rec		LS-300 🕤 💽 G
**	Media I/O >	System settings	
	Video >	Device identification	
_	Storage		
	Scheduler	Hostname :	Hostname follows RFC-952 internet host table specification.
±	Upload	LS-300	
P.	Interactive	Device description :	_
¥	System 🗸	LS-300	
ď		Brand :	
	System settings	AREC Inc.	
	Network	Model :	
	Firmware	LS-300	
	Configuration	Out of an and a set	
•	Account	Serial number :	
		LS3002137V0002	
		MAC :	
		BC:BA:E1:21:21:21	

2. Check the 10th digit of the S/N. If it is "V", then the device has the new hardware. If it is "0", it has the original hardware and is not compatible with the firmware series described in this release note.





New Features and Modification of VA1


- 1. Differential audio input with phoenix type connector is "only" available on *LS-300*, *LS-400* and *KL-3T*.
- Audio Noise Reduction (Line-in/Mic-in) It can reduce the background noise that is present in recordings.
- Audio Gain Control (Line-in/Mic-in) Both balanced (Phoenix) and unbalanced (3.5mm) audio inputs have "Gain Control".
 - Line-in (Unbalanced/Balanced): 3-step gain Low, Medium, High
 - Mic-in/BT-Mic: 30-step gain

Advanced settings				
Line-in (Unbalanced) gain :				
Medium	\sim			
Line-in (Balanced) gain :				
Low	\sim			
Mic-in gain				
•••••	14			
Wireless Mic gain				
••••	10			
Noise reduction :				
OFF	\sim			
Default				

4. Equipped with one RE-232 camera control port

The same RS-232 port can now send commands for camera control while receiving commands from control systems.

* It can only control one camera, for additional cameras, USB-RS-232 cables will still be needed.





New Features

N/A

Issues Fixed & Modification

V2.11.27.68

- Fix "An error message appeared after disabling and enabling OSD menu."
- Fix "The 'Cancel' button disappeared when selecting a file with a long filename while importing an ICS calendar file."
- Fix "When OSD menu was disabled, it still appeared after rebooting."
- Supports Japanese.
- Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.