

Release Note DS-AC1 v1.0.0.12

New Features

N/A

Issues Fixed & Modification

v1.0.0.12

- Fixed “IR Learning sometimes failed with error code 0x00000000.”
- Fixed “Lack of video indication on the GUI during the firmware update process.”
- Fixed “Long-pressing on a touch panel to control the GUI would call out a menu that blocked control of all GUI items.”
- Fixed “Control tab pages (Display A-C/Control/Media Station/IPcam Control) could not be hidden.”
- Fixed “The GUI would get stuck after controlling a PTZ camera using RS-232 or Visca-over-IP.”
- Fixed “The power consumption report could not be cleared.”

Limitation & Known Issue

- The video indication of firmware update appears more than 1 minute after the update starts.
- IR I/O now only supports the NEC protocol.
- **Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.**