


Release Note DS-4CU VA1 v6.1.10.19



(This version is only compatible with the new HW version – VA1)

Device Hardware Version

1. Please find your device serial number (S/N), it can be found either on the label or on the web Administration page.



2. Check the 10th digit of the S/N. If it is “V”, then the device has the new hardware. If it is “0”, it has the original hardware and is not compatible with the firmware series described in this release note.



New Features

Added support of “Audio-Technica ATND1061”

Support List (Keep Adding):

Brand	Model
Audio-Technica	ATND1061 Beamforming Ceiling Array Microphone ATUC-50CU Digital Wired Conference System ATUC-IRCU Hybrid Infrared Conference System
BOSCH	CCS 1000 D Digital Discussion System DCN-CCU2 Central Control Unit DICENTIS Wireless Conference System DICENTIS Wired Conference System <i>*Beta</i>
BxB	FCS-6350 Conference Main Control Unit
HAYACO	WMC-240G Digital Wireless Main Controller
SENNHEISER	AND CU1 Digital Discussion Central
SHOW	DCS-100M Digital Conference System
SHURE	DDS 5900 Digital Discussion System MXA Array Microphones – MXA920/MXA910/MXA710/MXA310 Shure MXW Wireless Microphone Systems Shure MXCW Digital Conference Systems
TELEVIC	D-Cerno AE & Coferno (Plixus AE-R/MME/Confidea WAP G4) D-Cerno CU-R (TCCP API) Plixus Core (CRP 6.x, CoCon API for Plixus AE-R/MME)

Issue Fixed & Modification

- Fixed “Overlay, background, or Theme IDs could not be configured with values over 100.”
 - Fixed “Disabling tracking while connected to a Bosch Dicientis Wired System could cause the tracking function to crash.”
 - Fixed “When one of the Overlay/Background in the admin Theme reaches 256 images, the ‘+’ icon of the other asset that has not yet reached 256 images disappears after canceling the edit.”
 - Fixed “When using the chairman microphone with Bosch DCN-CCU2, DS-4CU didn’t respond to the microphone’s signal.”
 - Added support for the Bosch Dicientis Wired microphone system.
 - Fixed “The ‘Camera Control’ page wasn’t fully loaded every time and may require a refresh to recover.”
 - Fixed “More than 100 Overlay or Background images could not be added.”
-
- **Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.**