Release Note LS-410 v1.0.0.36

New Features

N/A

Issue Fixed & Modification

V1.0.0.36

- Fixed "[Random] The web preview in each video input's properties page could appear as a green screen if the video source resolution was smaller than the streaming setting."
- Added support for an HTTP API that assigns videos to export to a front USB drive using the recording ID.
- Added support for Kaltura schedule iCal format with UID.
- Fixed "Changes to a child event from a recurring event on Kaltura were not applied to the schedule recording function."
- Fixed "Setting SRT streaming with a 1024-character stream ID could crash the web page."
- Fixed "Inserting an SRT URL starting with 'srt://' in the video input settings triggered an 'Invalid URL' error."
- Fixed "The HDMI-in 2 audio volume slider on the Online Director page wasn't synchronized when adjusting the volume via API."
- Fixed "Applying a customized 1080P Overlay in a theme caused the thumbnail to appear distorted."
- Fixed "[Random] The system could crash after applying changes to the video settings of channel 3."
- Fixed "[Random] loading the web preview could cause a system crash."
- Fixed "The RTMP connection test failed when additional parameters were included."
- Fixed "[Random] Changing the video source to 'None for video inputs (except channel 1) could cause a system crash."
- Updated USB Storage recording setting to include two modes:
    - Record to USB: Saves recordings only to the USB storage.
    - Copy to USB: Saves recordings to local storage and additionally copies the mixed video to the USB storage.
- Modified the maximum number of themes to 50.
- Modified HID behavior so that the cursor automatically hides after being idle for 2 seconds.
- Fixed "[Random] Recording videos might contain a pause image."

- Fixed "Refreshing the browser while on the video channel properties page could cause the web preview service to crash."
- Fixed "Audio shift settings were not applied in the web preview."
- Fixed "The deletion of a recurring event on Kaltura was not applied to the scheduled recording function."
- Updated the icon of the Loop-through (HDMI) button on the GUI.

- Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.