

## Release Note LS-410 v1.0.0.30

### New Features

N/A

### Issue Fixed & Modification

#### V1.0.0.30

- Fix “Device description with a long string appears distorted on the mini controller web page”.
  - Support SRT for video sources and live streaming.
  - The settings for the stream server have been relocated to the Streaming page from now on.
  - Fix “4K overlay images appear distorted in the mini controller web page”.
  - Add an on/off switch for the GUI menu bar.
  - Add a switch to hide/show the playback (export) button on the GUI menu.
  - Modify the handshaking mechanism of web preview. The Station will only use local handshaking methods from now on.
  - Fix “[Random] Overlay disappearing after returning from video playback when the transition effect is enabled”.
  - Fix “[Random] System crash and GUI stuck on the ‘loading’ icon after applying a change of video sources”.
- 
- **Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.**